026683




COPY NO. 2/

DDC

JUL 12 1976

العاككا

TECHNICAL REPORT 4870



SAMUEL KAHN ROBERT F. SAYER

**JUNE 1976** 

APPROVED FOR PUBLIC RELEASE, DISTRIBUTION LIMITED.

PICATINNY ARSENAL DOVER, NEW JERSEY The findings in this report are not to be construed as an official Department of the Army position.

## DISPOSITION

Destroy this report when no longer needed. Do not return to the originator.

PA-TR-4876

**UNCLASSIFIED** SCURITY CLASSIFICATION OF THIS PAGE (When Date Box MEAD INSTRUCTIONS REPORT DOCUMENTATION PAGE SECTION OF CAVALOR Technical Jepan L. TYPE OF REPORT & PERIOD COVERED TESTING OF MEAAL TIME FUZE WITHOUT G PELLETS . C. PERPORNING CHE. REPORT NUMBER . AUTHORE S. CONTRACT OR SHANT NUMBERYOU Samue 1/Kahn Robert F. Sayer necking one American name and appares munition Development & Engineering Directorate Picatinny Arsenal Dover, NJ 07801 11. CONTROLLING OFFICE HAME AND ADDRESS Jung 23 Unclassified 184 DECLARMFICATION DOWN STADING DISTRIBUTION STATEMENT A Approved for public release; Distribution Unlimited 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 30, if different from Report) Approved for public release, distribution unlimited. 16. SUPPLEMENTARY HOTES 19. KEY WORDS (Continue on revocas side il necestary and identify by block number) Fuze, Time, M84Al Transfer pellet Elimination ETRACT (Continue on severae able if necessary and identify by block samber)

This report represents the result of a series of tests performed on the M84A1 fuze used on 81 mm illuminating cartridges. The fuzes were modified by removal of the type C pellet from the graduated time train rings and by substituting cored B pellets.

Static testing at both 20- and 30-second settings yielded no failures due to non-transfer of ignition from the upper to the graduated time train rings in 1200 fuzes tested. The feasibility of eliminating the C pellet was verified.


DD 1 JAM 20 1473 EDITION OF 1 NOV SE N. CONDUCTE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PASE (When Data Saturda)

### **ACKNOWLEDGMENT**

The authors are grateful for the valuable assistance provided by Frank Puccio, Gaetano Tuorto and Bernard Uszenski of the Industrial Operations Directorate in preparation and testing of the modified M84A1 Fuze.





## TABLE OF CONTENTS

	Page No.
Background	1
Details of Testing	3
Conclusions	3
Recommendations	7
Distribution List	19
Tables	
1 M84Al fuze function time, Lot MSO 1-8, Production fuze for control, Pellet C removed	8
M84Al fuze function time, Lo+ MSO 1-9 Production fuze for control, Pellet C removed	10
3 M84Al fuze function, Group T-1, Picatinny pellets A, B, and D, B pellet 0.182 long	12
4 M84Al fuze function, Group T-2, Picatinny pellets A and D, PSI pellet B 0.217 long	14
5 M84A1 fuze function, Group T-3, Picatinny pellets A and D, Celesco pellet B 0.215 diameter	16
Figures	
1 Time fuze M84A1	2
Pellets, ignition 9234458	5
3 Graduated time train ring assembly 9232791	5

### BACKGROUND

The M84A1 (see Fig 1), for use on the M301A3 81 mm illumination cartridges, is a pyrotechnic time fuze settable from 0 to 50 seconds. The primer initiates functioning by igniting the type A pellet in the upper time train ring. This in turn sets off the tungsten delay powder which burns a predetermined amount of time depending on the set time. The B pellet in the graduated ring is then ignited and transfers to the tungsten delay powder via the C pellet. The D pellet in the body is ignited next and sets off the black powder expulsive charge which causes candle separation and ignition.

Prior to 1968 the pellets (A through D) were of zirconium nickle composition. Since this resulted in less than desired functioning of the fuze, the pellets were changed to boron-potassium nitrate composition. With the zirc pellets, both B and C pellets were required for proper ignition transfer. This is not the case with the BKNO3 pellets which produce a hotter flame front. However, due to the South East Asia (SEA) situation, fuzes required for verification testing were not available. Fuzes were finally made available from rejected Maxson Corp fuzes.

Claims against the Government were initiated first by Maxson Corp in 1973, and then by Thiokol in 1975. They claimed that fuze duds were caused by failure of ignition transfer between the upper time train ring and the graduated time train ring due to the C·pellet being ejected through the vent washer. A small number of exploratory tests were made without washers and C pellets. All test samples resulted in proper ignition transfer, thereby suggesting a technical weakness in the claim. Since the sample size tested was considered to be statistically small, a larger sample size was tested. The test results are detailed in this report.

TIME FUZE M84AI

Fig 1 Time fuze M84A1

### DETAILS OF TESTING


The fuzes used for these tests were manufactured by Maxson Corporation in 1973 and subjected to adverse storage conditions, i.e., fuzes were left out in the rain in open containers. To determine the usability of the fuzes after being exposed to these conditions, 300 fuzes were statically fired after removal of the window, vent washer, and C pellets (see Tables 1 and 2). Half the fuzes were fired at the 20-second and half at the 30-second setting, resulting in two duds. The two duds were caused by a missing D pellet and blockage of the transfer hole by a crumpled felt washer.

Additional testing of 900 fuzes was conducted using cored B pellets (see Fig 2) that produce a hotter and faster flame front for initiation of the tungsten delay powder. The core holes in all cases were 1.40 mm (0.055 in.) ± 0.13 mm (0.005 in.). Prior to testing, the fuzes were disassembled and all pellets (A, B, C, and D) were removed. The graduated time train rings (see Fig 3) were modified by increasing the depth of the B pellet hole from 3.94 mm (0.155 in.) + 0.13 mm (0.005 in.) to 4.83 mm (0.190 in.) + 0.13 mm (0.005 in.). The fuzes were then reassembled with new A and D pellets, with three different B pellets (see following list), and without C pellets; also without C pellet washers and windows.

Using 300 B pellets from each of the three sources, 900 fuzes were assembled. The fuzes were statically tested, half at the 20-second and half at the 30-second settings. No duds were encountered. The irregularities in the burning time were due to the unfavorable storage conditions of the fuzes prior to shipment to the Arsenal.

### CONCLUSIONS

The reliability demonstrated in each test group at both settings is 0.992 percent. This is comparable to reliability achieved in fuzes of the current configuration. Therefore, the results of the testing prove that the C pellet is redundant and can be safely removed to achieve proper ignition transfer from the upper to the lower time train rings.



	ANGLE	NONE	150+10	NONF	450±50
	و	210-212	217-012	182-012	337007
	2	1007191	191791	161±001	202±001
100	רבונבו	٨	മ	۵	E.
DADT NO	j	9234458-1	9234458-2	9234458-4	323445B-5

Fig 2 Pellets, ignition 9234458

Fig 3 Graduated time train ring assembly 9232791

### **RECOMMENDATIONS**

Ż

k iye

教学が上の主義

The C pellet should be eliminated, thereby reducing the cost of the fuze and avoiding handling of the pellet. Reduced handling would eliminate hygroscopic problems associated with the pellet, and consequently could lead to a reduction in the fuze dud rate.

The 5.51 mm (0.217 in.) - 0.30 mm (0.012 in.) length B pellet should be used even though all pellets functioned uniformly. The longer pellet will bring the flame front closer to the tungsten delay powder, thereby assuring a better transfer of ignition.

The drawings for the B pellet (9234458) and graduated time train ring (9232791) should be modified in accordance with the dimension in Figures 2 and 3.

Table 1

### M84A1 fuze function time Lot MSO 1-8 Production fuze for control Pellet C removed

# Fuze setting: 20 seconds

19.75	19.95	16.20
19.27	18.30	20.15
18.44	20.47	20.21
18.90	19.59	
18.37	14.39	
15.65	15.82	
19.28	16.45	
19.62	18.41	
19.75	19.48	
18.42	19.58	
18.84	12.98	
18.58	19.27	
18.84	19.28	
19.28	19.27	
20.24	19.05	
15.77	18.78	
19.33	19.78	
19.59	19.05	
19.45	19.08	
19.63	19.83	
19.66	19.72	
12.15	17.31	
DUD	19.04	
20.08	15.35	
20.30	19.92	
19.40	19.87	
19.17	20.11	
19.04	19.29	
19.50	19.15	
19.46	19.34	
16.55	19,99	
20.20	19.80	
19.70	19.60	
19.68	19.95	
14.21	20.97	
20.07	19.46	

Table 1 (Continued)

25.26	29.98	
29.25	28.68	
28.71	29.34	
29.62	29.36	
29.71	28.49	
29.12	29.01	
28.75	28.84	
28.35	29.09	
29.00	28.85	
29.34	28.82	
29.48	28.68	
28.72	20.75	
28.31	29.01	
29.05	28.54	
28.69	29.26	
29.07	28.46	
29.42	18.30	
29.27	28.53	
29.15	29.22	
28.92	28.87	
28.74	29.51	
28.59	30.05	
28.91	25.78	
28.36	21.33	
29.18	28.77	
29.43	29.22	
29.29	28.99	
29.07	29.62	
29.22	28.59	
29.54	29.05	
30.15	28.92	
30.21	29.18 28.80	
28.97	20.00	
29.81		
29.57		
28.42 28.85		
28.63 29.62		
29.02 28.92		
29.28		
29.24		
29.55		
£3.33		

Table 2

### NB4A1 fuze function time Lot MSO 1-9 Production fuze for control Pellet C removed

18.91	19.63
19.68	20.17
19.67	19.55
19.66	19.20
19.65	19.06
19.74	19.34
19.10	19.07
19.32	20.09
19.67	18.71
19.65	19.40
19.52	19.58
19.27	19.43
20.04	19.35
19.78	19.55
18.65	19.59
19.45	19.32
19.69	20.17
20.61	18.75
20.06	19.39
20.20	19.57
19.20	18.70
18.92	19.97
19.70	19.57
20.16	19.60
20.12	20.27
19.44	19,63
18.80	19,90
20.09	19.86
18.71	20.41
20.65	19.04
19.11	19.53
19.17	18.36
19.86	19.18
12.77	19.17
19.56	19.50
19.95	<b>18.9</b> 5
20.44	19.40
	20.30

Table 2 (Continued)

28.95	28.91
29.74	29.55
28.89	29.21
29.18	28.85
28.98	28.79
28.92	28.68
29.50	DUD
28.63	28.29
29.07	29.39
28.30	28.44
28.35	28.71
29.80	28.84
28.91	29.03
28.73	28.44
29.20	29.22
28.82	28.60
29.21	28.05
28.41	29.09
28.65	29.13
29.50	28.66
28.68	28.67
29.50	28,65
28.34	28.79
29.23	29,30
DUD	28.74
28.74	28.62
29.23	28.77
29.22	29.15
29.49	28.77
29.23	29.75
29.23	28.78
28.80	27.95
29.41	29.20
28.55	
28.75	
28.94	
29.86	
29.45	
28.89	
29.68	
28.74	
28.64	

Table 3

## M84Al fuze function Group T-1 Picatinny pellets A, B, and D B pellet 0.182 long

19.99	20.00	20.50	19.05	20.65
20.31	19.71	20.65	19.55	19.89
19.94	20.72	20.65	20.22	
20.60	19.63	20.26	20.07	
20.56	20.10	20.80	17.70	
20.81	20.25	20.93	20.45	
20.21	20.24	20.45	20.49	
21.03	19.94	20.96	20.37	
21.62	20.04	22.55	15.26	
21.55	20.73	20.60	21.65	
20.05	20.42	20.00	17.95	
20.62	20.84	20.81	20.82	
20.65	19.95	19.74	20.62	
19.68	20.92	20.47	20.26	
20.60	20.50	20.40	16.20	
20.03	19.84	20.54	19.87	
20.57	20.81	20.34	19.76	
21.00	20.14	20.45	18.50	
20.65	20.65	20.12	20.27	
20.82	20.22	19.51	15.04	
20.09	19.96	20.42	20.96	
21.62	20.47	20.15	20.65	
20.95	20.85	20.32	20.62	
21 85	21.46	21.15	20.33	
19.95	20.50	20.26	19.66	
20.29	20.59	20.51	20.51	
19.48	21.43	20.85	18.21	
20.78	20.70	21.60	20.11	
21.32	21.11	20.58	20.36	
20.70	20.01	20.74	20.42	
20.42	20.07	19.03	20.18	
20.55	19.85	21.21	20.67	
20.75	21.51	20.62	19.98	
21.30	20.65	19.78	21.19	
20.48	20.29	16.65	20.89	
20.33	20.05	19.70	18.30	
20.72	20.56	20.49	17.35	

Table 3 (Continued)

30.25	29.85	30.62	29.32
29.71	29.70	28.09	29.82
29.98	29.90	30.11	29.33
23.37	30.70	30.04	29, 69
29.45	31.80	24.00	30.72
30.58	29.13	28.95	29.75
29.91	29.66	22.25	27.92
30.03	30.16	29.48	29.26
28.02	28.73	29.74	26.60
28.09	28.93	29.57	29.80
26.70	28.72	30.35	22.92
29,95	29.90	30.90	23.48
28.89	29.48	29.54	30.14
29.15	30.23	30.30	30.73
28.80	29.09	29.24	25.25
27.75	29.57	29.95	21.20
28.94	30.00	29.90	30.74
29.73	30.30	29.56	21.18
27.60	28.95	28.63	30.75
20.44	22.92	29.73	29.20
28.90	30.51	29.11	19.03
29.72	30.12	27.00	16.00
20.81	29.44	32.05	28.50
29.99	29.50	29.25	30.02
29.50	30.61	29.82	
28.97	29.69	22.69	
28.87	29.75	20.98	
29.90	29.97	30.01	
30.04	29.65	29.76	
28.90	30.17	25.32	
30.40	30.02	29.83	
28.65	30.15	29.45	
29.42	30.29	23.50	
28.58	25.89	31.00	
29.10	31.12	29.95	
29.90	29.88	29.35	
24.23	30.13	30.38	
29.96	30.65	30.15	
29.99	29.00	29.51	
29.52	29.14	30.25	
29.83	30.40	29.29	
30.08	29.70	30.26	

Table 4

### M84A1 fuze function Group T-2 Picatinny pellets A and D PSI pellet B 0.217 long

Fuze setting: 20 seconds

22.37	21.30	20.00	19.10
19.75	19.45	20.52	20.28
20.82	20.76	19.64	20.19
19.41	20.38	20.61	19.80
19.29	20.35	20.27	20.36
19.44	20.51	21.03	20.05
20.09	20.58	20.02	19.75
20.52	20.24	16.11	19.92
19.39	20.49	19.84	19.41
19.50	20.57	19.99	19.68
19.65	19.82	20.38	20.18
20.12	20.08	20.56	19.50
14.94	20.34	19.21	20.25
19.52	20.05	20.03	15.61
20.21	20.35	20.55	19.68
21.16	20.24	19.32	19.65
19.89	20.06	19.78	20.49
20.05	16.25	19.34	19.87
18.39	19.92	19.49	15.87
20.15	20.32	17.60	19.93
19.70	20.14	19.15	20.27
19.63	19.56	19.48	19.95
19.77	19.78	20.01	19.87
19.96	16.08	20.16	20.83
19.76	20.04	20.92	18.43
19.56	20.57	19.65	29.85
20.26	19.68	20.39	20.44
20.06	19.57	19.73	20.07
19.42	20.40	20.58	20.13
20.05	19 - 74	19.65	20.25
19.59	19.02	19.30	20.68
20.15	20.55	20.26	20.35
19.73	20.33	20.51	20.32
18.62	20.56	19.80	14.61
20.23	20.75	16.04	19.78
19.75	18.75	20.18	20.02
20.32	20.27	20.81	
18.42	19.78	18.32	

Table 4 (Continued)

30.58	29.10	.0.35	29.65
39.15	29.25	30,15	30.14
29.34	29.00	30.25	28.50
29.40	30.35	29.72	29.92
29.23	28.98	29.90	22.38
23.88	29.02	29.05	23.58
29.20	28.89	30.49	29.47
29.30	30.00	30.36	29.02
28.73	24.75	29.88	26.67
29.99	29.90	29.80	29.34
28.73	29.66	23.50	29.94
29.83	29.38	30.40	30.72
29.68	29.80	30.16	32,23
29.23	29.88	30.98	30.09
29.24	26.52	30.52	31.02
29.67	30.00	30.28	29.88
29.20	30.72	29.70	30.36
29.34	29.65	30.02	29.77
28.94	24.60	28.40	30.02
29.14	30.62	29.21	30.95
29.72	30.48	30.92	30.68
30.35	29.42	29.02	30.12
29.35	30.42	29.47	29.90
30.19	29.35	30.21	20.46
30.08	29.53	29.69	
29.62	29.41	22.90	
29.12	29.44	29.57	
29.14	27.27	29.67	
29.30	30.41	30.10	
30.08	29.72	30.60	
29.65	30.45	30.10	
29.28	30.17	30,67	
30.22	30.76	25.38	
29.77	30.45	29.59	
29.86	29.78	26.28	
29.18	30.16	29.23	
30.29	30.40	29.41	
29.13	29.77	28.86	
28.97	30.20	29.45	
30.40	30.14	29.39	
29.48	26 . 24	29.38	
30.70	29.73	29.50	

Table 5

## M84Al fuze function Group T-3 Picatinny pellets A and D Celesco pellet B 0.215 diameter

20.92	20,22	19.57	20.35	10 10
19.92	19.55	19.83	19.56	18.10
20.75	19.36	20.00	19.84	19.11
20.07	19.01	19.45	19.07	
20.62	19.93	20.37	19.61	
19.76	19.21	20.16	19.44	
19.77	19.28	20.20	19.95	
19.99	18.80	20.14	19.63	
20.32	19.42	19.87	19.90	
19.82	19.25	20,36	19.40	
19.43	19.76	21.14	20.19	
19.96	19.27	18.87	19.15	
19.88	19.95	19.64		
20.25	20.06	19,27	20.17	
20.03	19.85	20.12	20.45	
20.95	19.24	19.05	20.14	
19.72	19.32	19.58	19.87	
19.35	20.37	19.32	20.35	
19.10	19.08	20.06	19.79	
19.42	19.14	18.50	19.84	
20.43	20.61	20.15	19.54	
20.00	19.05	19.97	18.71	
19.11	19.44	20.06	19.63	
19.46	19.50	19.03	20.57	
18.66	19.95	19.73	20.72	
19.24	19.12	19.92	20.40	
19.79	20.34	20.00	20.27	
20.00	19.58	19.37	20.16	
19.72	19.28	20.32	21.27	
19.47	20.18		19.70	
20.12	19.59	18.72 19.60	20.34	
20.59	19.36		20.52	
18.66	19.74	19.55	19.73	
19.77	19.21	20.29	19.99	
19.33	19.43	19.60	19.83	
19.14	19.95	19.79	20.51	
20.41	19.82	20.01	20.37	
· <del>-</del>	13.02	19.53	19.70	

Table 5 (Continued)

28.86	29.17	22.47	28.95
29.80	29.40	28.34	29.50
29.48	29.95	29.46	29.67
29.37	29.45	29.23	29.38
29.28	29.82	30 - 21	29.48
29.12	29.32	29.50	29.70
30.00	29.28	29.32	29.32
29.55	19.32	28.80	29.79
29.30	29.45	28.05	28.47
29.09	29.52	28.79	29.05
24.40	28.68	29.01	30.26
29.31	29.86	29.70	29.35
29.12	29.87	29.21	29.15
29.91	29.65	29.89	29.20
29.87	29.31	29.38	30.00
29.72	29.56	30.32	29.88
28.70	29.27	28.80	29.15
29.56	28.67	29.40	29.30
28.98	30.03	29.67	30.06
29.76	<b>29.3</b> 5	29.30	29.78
28.96	<b>2</b> 9.42	30.19	30.60
29.30	28.80	29.70	29.21
28.76	28.79	29.60	29.77
29.30	28.95	29.15	29.37
29.80	30.11	28.83	
29.47	29.91	29.11	
28.91	29.40	29.25	
29.18	29.21	29.38	
23.49	29.75	29.25	
28.80	29.10	29.37	
29.58	29.15	29.56	
29.51	30.56	29.22	
28.79	29.38	28.85	
29.37	30.09	29.57	
29.50	29.76	30.12	
29.55	29.20	28.65	
28.03	29.92	29.32	
23.34	29.62	29.05	
29.20	29.73	28.90	
29.97	29.11	30.02	
29.91	30.00	30.27	
29.15	29.27	29.51	

# DISTRIBUTION LIST

	Copy No.
Commander	
Picatinny Arsenal	
ATTN: SARPA-AD-F	1
SARPA-AD-F-E-3, Mr. S. Kahn	3-10
SARPA-AD-F-D	11-13
SARPA-QA-A-F, Mr. R. Sayer	14-15
SARPA-TS-S	16-20
Dover, NJ 07801	
Defense Documentation Center	21-32
Cameron Station	
Alexandria, VA 22314	
Commander	
U.S. Army Materiel Development	
and Readiness Command	
ATIN: DRCRD-WC	33
Alexandria, VA 22304	
Commander	
U.S. Army Armament Command	
ATTN: DRSAR-RDF	34-37
DRSAR-RUT	38
DRSAR-PPC-AM, Mr. G. Waldo	39-41
DRSAR-GC, Mr. D. Harrington	42-43
DRSAR-ASF	44
Rock Island, IL 61201	
Commander	
Harry Diamond Laboratories	
ATTN: AMXDO-DAB	45-46
Washington, DC 20438	